
CITY OF BALTIMORE WET W SMOKE AND DYED W	Page 1 of 3	
Sewershed: JONES FALLS	Company: REI/DRAYCO	Date: 06/12/2008
Test to be Performed: SMOKE	Ground Condition: DRY	Supervisor: ER
Manhole ID: S37MM_047MH	Test ID: 0994-366	Notifications Made:_X (Residents, Fire, 311)

Field Sketch: (Show All Manholes with Numbers, Blower Placement Location, Sandbag or Isolation Locations, Street Names, Building Addresses and Locations, Defect Locations and Photograph Numbers)



TOTAL: 397.3 LF

CITY OF BALTIMORE WET WEATHER CONSENT DECREE SMOKE AND DYED WATER TESTING FORM							Page 2 of 3		
Sewershed: JONES FALLS			Company: REI/DRAYCO				Date: 06/12/2008		
Test to	be Performed:			Ground	Condition	:		Supervisor:E.R	
Smoke	e:X	yed Water:		Dry: _X_	Dar	mp: W	/et:	. — —	
SmokeX Byed water			Dry: _X Damp: Wet:				Notifications Made:X		
Manhole ID: S37MM_047MH			Test ID: 0994-366				(Residents, Fire, 311)		
	Sketch: (Showons, Street Nam							_	
Defect	,			Source	,		Drainage	9.00	
No.		Address		Туре	Location	Sector	Area	Severity	Photo Number
	703 E. 20TH S	Γ		0218	12	01	200	03	366_OB01-01
-	700 L. 20111 O	1 -		02 0		•			000_020:0:
				OBSERV	ATION	CODES			
	Source Type	Location	Sector	Severity		Source Type	Location		
01	Main Sewer	Paved Concrete	Public	No Smoke	10	MH Frame S	Non-Paved		
02	Service Line	Paved Asphalt	Private	Trace	11	Storm Drain	Field/Woods		
	Cleanout	Paved Other		Moderate		Catch Basin/			
	Downspout	Driveway		Major		Storm Manh			
	Area Drain	Sidewalk				Storm Ditch	Other		
	Driveway Drain	Curb				Excavation			
	Stairwell Drain	Yard- Front			16	Other			
	Foundation Drain	Yard-Back							
09	Building Interior	Yard- Side							

PAGE 3 OF 3

CITY OF BALTIMORE SMOKE TESTING OBSERVATION SUMMARY JONES FALLS SEWERSHED

BALTIMORE CITY PROJECT 994 REI/DRAYCO

Unique Test ID: 366	Date: 06/12/2008	Basin: JF-19
Defect No: OB01	Supervisor: E.R.	Dye Test Recommended: N
House No: 703	Street Name: E. 20TH	Street Type: ST.
Source Type: 16	Location: 12	Severity: 03

Sector: 01 Drainage Area: 200

Comments: SMOKE COMING FROM MANMADE HOLE IN GROUND AT WORKSITE IN ALLEY BEHIND

ADDRESS.

SMOKE TEST PHOTOGRAPHS



Photograph No: OB01-01 Filename: 0994-366_OB01-01.jpg